



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) _____ **Control Number: 1339928**

2. Premise No. 234 Street Name West 27 Street Borough Manhattan Zip 10001

3. AKA _____ Type of Facility Residence BIN 1014238 Block 776 Lot 58

4. Building Owner Core Scaffold Systems Inc. Address 417 Myrtle Avenue, Suite 14

5. City Brooklyn State NY Zip 11205 Contact Person Mendim Dobrova

6. Tel. # (914) 278-6038 Fax # _____ Email dob@corescaffold.com

7. Description of the Entire Scope of Work
Installation of pipe scaffold (on East Facade).

8. I, MARY HARTIGAN, have conducted an asbestos investigation on
Name of Certified Asbestos Investigator
09/09/2017 9:15AM-9:30AM in accordance
Date(s)
with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

☐ a. portion(s) of the premises affected by the work is free of asbestos containing material (ACM).

☒ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.

☒ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: 1415 sq. ft. _____ linear ft.
Specify locations (attach additional documents as necessary):
Masonry and Mortar (1375 sq/ft) and Flashing (40 sq/ft) are assumed asbestos.

☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

FLOOR	DESCRIBE SECTION OF FLOOR	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT	ASSUMED ACM
OSP	East Facade Proposed Scaffold Location Only	Masonry and Mortar (1377 sq/ft)	0	Yes	Yes
OSP	East Facade Proposed Scaffold Location Only	Flashing (40 sq/ft)	0	Yes	Yes

10. ANALYTICAL LABORATORY:


NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
------	--------------------------------	--------------------------

I hereby declare the information provided herein is true and complete

MARY HARTIGAN 9/10/2017 120566 12/7/2018
DEP Certified Asbestos Investigator's Signature *Date* *Certificate Number* *Expiration Date*

Tel. # (914) 494-2285 Fax # _____

Email mhartigan127@aol.com



The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

Is it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

ASBESTOS ASSESSMENT REPORT



11. NYS DOL Asbestos Handling license # 61539 Company Name Environmental Experts, Inc.

I hereby declare the information provided herein is true and complete

MARY HARTIGAN 9/10/2017 120566 12/7/2018
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (914) 494-2285 Fax # _____
Email mhartigan127@aol.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



Is it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.



25357191