




NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) _____ **Control Number: 2048477**
2. Premise No. 3667 Street Name PAULDING AVENUE Borough Bronx Zip 10469
3. AKA 3667 - 3667 Type of Facility _____ BIN 2058853 Block 04686 Lot 0005
4. Building Owner Patricia Billett Address 3667 Paulding Avenue
5. City Bronx State NY Zip 10469 Contact Person Carlos Sosa
6. Tel. # (914) 954-9618 Fax # _____ Email csmrdesigns@yahoo.com

7. Description of the Entire Scope of Work

INTERIOR RENOVATION OF EXISTING THREE FAMILY HOUSE. NO CHANGE IN USE, EGRESS OR OCCUPANCY. (NOTE: This acp5 is issued strictly as per job description if there is any change, amending plans, adding or extending work area, contact person or owner must call immediately the investigator for a re-inspection)

8. I, JULIO CORPORAN, have conducted an asbestos investigation on

Name of Certified Asbestos Investigator

10/18/2012 in accordance

Date(s)

with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☒ a. portion(s) of the premises affected by the work is free of asbestos containing material (ACM).
☐ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
☐ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: _____ sq. ft. _____ linear ft.
Specify locations (attach additional documents as necessary): _____

☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

FLOOR	DESCRIBE SECTION OF FLOOR	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT	ASSUMED ACM
Cellar	North center next to staircase	Concrete Cement Foundation wall Approx 360 SF	1	No	No
Cellar	North west at rear end by boiler	Ceiling Sheetrock Approx 10'x 8'= 80 SF	1	No	No
Cellar	Northwest at rear end by boiler	Ceiling Plaster 1st Layer Approx 10'x 8'= 80 SF	1	No	No

I hereby declare the information provided herein is true and complete

JULIO CORPORAN 10/31/2012 119167 8/17/2014
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (718) 415-6360 Fax # (718) 889-2373 Email Julio.Corporan@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



2550408



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



Cellar	Northwest at rear by boiler	Ceiling Plaster 2nd Layer Approx 10'x 8' = 80 SF	1	No	No
Cellar	South center	Concrete Cement Floor Approx 20'x 45' = 900 SF	1	No	No
1st Floor	Northeast by entrance door	Linoleum Floor Tile Approx 5'x 20' = 100 SF	1	No	No
1st Floor	North center at staircase from cellar to 1st floor	Concrete Cement Approx 10'x 5' = 50 SF	1	No	No
1st Floor	Northeast next to stairs going to 2nd floor	Concrete Cement Wall Approx 20'x 9' = 180 SF	1	No	No
1st Floor	Northeast next to staircase going from 1st to 2nd floor	Wall Plaster Approx 20'x 9' = 180 SF	1	No	No
2nd Floor	Southeast at bedroom	Sheetrock Approx 20'x 40' = 800 SF	1	No	No
2nd Floor	Southeast at bedroom/Living area	Ceiling Plaster Approx 20'x 40' = 800 SF	1	No	No
2nd Floor	Southwest at rear end	Floor Carpet Approx 20'x 40' = 800 SF	1	No	No
2nd Floor	North center near staircase	Carpet Floor Tile Approx 9'x 5' = 45 SF	1	No	No
2nd Floor	Northeast at front bedroom	Carpet Floor Tile Approx 7'x 8' = 56 SF	1	No	No
2nd Floor	Southeast at bedroom	Drywall Approx 35'x 8' = 280 SF	1	No	No
2nd Floor	South center	Wall Plaster 1st Layer Approx 35'x 9' = 315 SF	1	No	No
2nd Floor	South center	Wall Plaster 2nd Layer Approx 35'x 9' = 315 SF	1	No	No
2nd Floor	North center next to staircase	Drywall Approx 20'x 8' = 160 SF	1	No	No
2nd Floor	North center at middle of living room	Wall Plaster Approx 40'x 8' = 320 SF	1	No	No
2nd Floor	Southeast at rear bedroom	Ceiling Drywall 10'x 10' = 100 SF	1	No	No
2nd Floor	Southwest at rear bedroom	Gypsum Board Approx 30'x 9' = 270 SF	1	No	No
2nd Floor	Southwest at bedroom	Wall Plaster Approx 30'x 8' = 240 SF	1	No	No

10. ANALYTICAL LABORATORY:

NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
Atlas Environmental Lab	11999	10/19/2012


11. NYS DOL Asbestos Handling license # 58447 Company Name NYC Asbestos Surveys Corp.

I hereby declare the information provided herein is true and complete

JULIO CORPORAN 10/31/2012 119167 8/17/2014
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (718) 415-6360 Fax # (718) 889-2373 Email Julio.Corporan@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



2550408