



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

ASBESTOS ASSESSMENT REPORT

RECEIVED

5/1/2016

DEP
ASBESTOS CONTROL
PROGRAM

FEE PAID

1. NYC DOB Job # (if applicable) _____ **Control Number: 4239984**
2. Premise No. 64-85 Street Name Booth Street Borough Queens Zip 11374
3. AKA _____ Type of Facility Residence BIN 4072156 Block 3085 Lot 55
4. Building Owner SW Management LLC Address 145 Huguenot Street, Suite 503
5. City New Rochelle State NY Zip 10801 Contact Person Wendy Hwang
6. Tel. # (914) 637-6200 Fax # _____ Email whwang@swmanagement.com
7. Description of the Entire Scope of Work
Installation of pipe scaffold (19444 sq/ft on facade).

8. I, MARY HARTIGAN, have conducted an asbestos investigation on
Name of Certified Asbestos Investigator
04/30/2016 6:30AM-6:45AM in accordance
Date(s)
with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the
- ☐ a. portion(s) of the premises affected by the work is free of asbestos containing material (ACM).
- ☒ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
- ☐ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: _____ sq. ft _____ linear ft.
Specify locations (attach additional documents as necessary): _____
- ☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

FLOOR	DESCRIBE SECTION OF FLOOR	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT	ASSUMED ACM
OSP	Facade	Masonry, Mortar, Stone, Concrete, Flashing/Waterproofing and Caulking are assumed asbestos. Less than 10 sq/ft will be disturbed to secure scaffold.	0	Yes	Yes

10. ANALYTICAL LABORATORY:

NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
------	--------------------------------	--------------------------

I hereby declare the information provided herein is true and complete

MARY HARTIGAN 5/1/2016 120566 12/7/2016
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (914) 494-2285 Fax # _____Email mhartigan127@aol.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATORIs it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.



25252724



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

ASBESTOS ASSESSMENT REPORT



11. NYS DOL Asbestos Handling license # 61539 Company Name Environmental Experts, Inc.

I hereby declare the information provided herein is true and complete

MARY HARTIGAN 5/1/2016 120566 12/7/2016
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (914) 494-2285 Fax # _____

Email mhartigan127@aol.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



Is it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No



25252724

5/1/2016 3:43:25 PM

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.