

Philip A. Robinson
NYC Licensed Electrical Contractor
235 Fifth Avenue Brooklyn, NY 11215
Phone: 718 783-6542 Fax: 718 228-8099
Email: vze4gyn5@msn.com

February 24, 2015

Mr. Mendel Rosenbaum ~ Building Manager
Stonehenge Management Co
120 West 97th Street
New York, NY 10025

Re: 167 East 82ed Street
Superintendant's apartment

Dear Sir:

This letter is to confirm the electrical hardwired smoke and carbon monoxide dector in the basement apartment has been reinstalled in the two bedrooms and hallway in the apartment.

These electrical hardwired smoke and carbon monoxide dectors are interconnected as required by NYC code and are installed on a seperated circuit in the apartment's electrical panel.

This work was reinstalled during the week ending February 20, 2015 and can be conferred by your super Mr. Timoteo Camano who gave us access.

If you have any further questions or concerns please feel free to call my office with your questions. This conforms to the requirements as outlined in the building code of the city of New York.

Yours truly,


Philip A Robinson