



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) _____ **Control Number: 4111381**
2. Premise No. 35-05 Street Name JUNCTION BLVD. Borough Queens Zip 11368
3. AKA _____ Type of Facility Commercial BIN 4043111 Block 01737 Lot 0060
4. Building Owner KI HYO PARK Address 486 HENRY ST.
5. City BROOKLYN State NY Zip 11231 Contact Person TL ENGINEERING P.C.
6. Tel. # (718) 353-8137 Fax # _____ Email _____
7. Description of the Entire Scope of Work
REPLACEMENT OF EXISTING ROOF TOP CONDENSING UNIT WITH MECHANICAL WORK ONLY.

8. I, CHANG BAE SEO, have conducted an asbestos investigation on
09/26/2013 in accordance
09/26/2013 Date(s)
with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the
☒ a. portion(s) of the premises affected by the work is free of asbestos containing material (ACM).
☐ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
☒ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: 3500 sq. ft linear ft.
Specify locations (attach additional documents as necessary):
ROOF-ASPHALT ROOFING FELT AND FLASHING
☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

FLOOR	DESCRIBE SECTION OF FLOOR	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT	ASSUMED ACM
ROOF	ASPHALT FLAT ROOF	ROOF-ASPHALT ROOFING FELT AND FLASHING(3,500 SF. NO DEMO WORKING. ONLY REPLACE HVAC MACHINE)	0	No	Yes

10. ANALYTICAL LABORATORY:


NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
------	--------------------------------	--------------------------

I hereby declare the information provided herein is true and complete

Chang Bae Seo 2/4/2014 116863 4/23/2014
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (212) 643-1133 Fax # (718) 679-9577 Email jseo777@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



Note: There is always a possibility of existing ACM inside the wall, or above ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.






NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



11. NYS DOL Asbestos Handling license # 64763 Company Name JSEO Studio Inc.

I hereby declare the information provided herein is true and complete



CHANG BAE SEO

2/4/2014

116863

4/23/2014

DEP Certified Asbestos Investigator's Signature

Date

Certificate Number

Expiration Date

Tel. # (212) 643-1133 Fax # (718) 679-9577 Email jseo777@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



Note: There is always a possibility of existing ACM inside the wall, or above ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.



25115057