



**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION**  
**Asbestos Control Program**  
 59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



1. NYC DOB Job # (if applicable) \_\_\_\_\_ **Control Number: 5072689**

2. Premise No. 70 Street Name JACKSON ST Borough Staten Island Zip 10304

3. AKA \_\_\_\_\_ Type of Facility Residence BIN 5106838 Block 00517 Lot 0019

4. Building Owner HYUN SANG SUNG Address 726 WOOLLEY AVENUE

5. City STATEN ISLAND State NY Zip 10314 Contact Person HACKJONG CHOI

6. Tel. # 6462851105 Fax # \_\_\_\_\_ Email \_\_\_\_\_

7. Description of the Entire Scope of Work  
 INTERIOR RENOVATION OF EXISTING HOUSE OF WORSHIP. REPAINTING,  
 REPLACEMENT OF FLOORING, WALL FINISHES, TILES, ETC. NO CHANGE  
 IN USE, EXITS OR OCCUPANCY

8. I, CHANG BAE SEO, have conducted an asbestos investigation on  
*Name of Certified Asbestos Investigator*  
03/20/2013, 05/01/2013, 05/07/2013 in accordance  
*Date(s)*

with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☒ a. portion(s) of the premises affected by the work is free of asbestos containing material (ACM).
- ☐ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.  
 Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
- ☒ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: 3000 sq. ft. \_\_\_\_\_ linear ft.  
 Specify locations (attach additional documents as necessary):  
CEILING-INSULATION(NO DEMO WORK)
- ☐ d. entire building is free of asbestos containing material (ACM).

**9. RESULTS OF ASBESTOS BUILDING SURVEY:**

| FLOOR           | DESCRIBE SECTION OF FLOOR | ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED | NUMBER OF SAMPLES ANALYZED | ASBESTOS PRESENT | ASSUMED ACM |
|-----------------|---------------------------|-----------------------------------------------------|----------------------------|------------------|-------------|
| CEL,001,& MEZZ. | CHURCH                    | NO ANY SUSPECTED ACBM(NO ANY DEMO WORK)             | 0                          | No               | No          |
| ROOF            | GABLE ROOF                | INTERIOR INSULATION(NO DEMO WORK)                   | 0                          | Yes              | Yes         |

I hereby declare the information provided herein is true and complete

CHANG BAE SEO 5/8/2013 116863 4/23/2014  
 DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (212) 643-1133 Fax # (718) 679-9577 Email jseo777@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL OF THE  
 NYC DEP  
 CERTIFIED  
 ASBESTOS  
 INVESTIGATOR



Note: There is always a possibility of existing ACM inside the wall, or above ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.



2576467



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



10. ANALYTICAL LABORATORY:

| NAME | ELAP # (NYS DOH CERTIFICATION) | DATE(S) SAMPLES ANALYZED |
|------|--------------------------------|--------------------------|
|------|--------------------------------|--------------------------|

11. NYS DOL Asbestos Handling license # 64763 Company Name JSEO Studio Inc.

I hereby declare the information provided herein is true and complete

CHANG BAE SEO 5/8/2013 116863 4/23/2014  
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (212) 643-1133 Fax # (718) 679-9577 Email jseo777@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL  
OF THE  
NYC DEP  
CERTIFIED  
ASBESTOS  
INVESTIGATOR



There is always a possibility of existing ACM  
inside the wall, or above ceiling, or under  
existing flooring. If any suspected ACM is found,  
all work should be stopped for reinspection.

5/8/2013 6:18:41 PM



2576467