

peter Himmelstein architect, pc
87 walker st., 6th floor
new york, ny 10013

212-966-3030

himmelstein.us

8/31/09

NYC Department of Buildings
280 Chambers Street
New York, NY 10007



Re: 308 West 19th St.
New York, NY

ALT I: 110214660

To whom it may concern:

Please allow this letter to serve as certification that all required carbon monoxide and smoke detectors have been installed in the above referenced building. Each detector has been tested and is fully operational.

If you have any questions, or require any further information, please do not hesitate to contact my office. Thank you.

Best Regards,

Peter Himmelstein, RA

