



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program

59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-51**NOT AN ASBESTOS PROJECT**ONLY
TYPEWRITTEN
FORMS WILL
BE ACCEPTED

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signature and seal are required. Submittal at the NYCDEP requires one copy of the form with original signature and seal.

2. Facility Address 262 West 24th Street Borough Manhattan Zip 10014
AKA _____ 3. Block 773 4. Lot 81
5. Building Owner Dundalk Management Inc Tel. # 212-243-7757
6. Address 50 Bank Street State NY Zip 10014
7. Contact Person Kenneth Nagin 8. Tel. # 212-243-7757
9. Description of the Entire Scope of Work
Renovate apartment 5B

10. Est. Start Date _____ ☒ As soon as permit approved Est. Completion Date _____ of the Entire Scope of Work.11. I, Anthony P. Nowicki Jr., have conducted an asbestos investigation on 9-10-08 in accordance with
Name of Certified Asbestos Investigator Date

Sections 1-16 and 1-27 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☐ a. premise to be demolished is free of any asbestos containing material (ACM).
☐ b. premise to be demolished contains 10 square feet or less or 25 linear feet or less of ACM.
☒ c. cumulative surfaces of structure(s) affected by the work are free of ACM.
☐ d. cumulative surfaces of structure(s) affected by the work contain 10 square feet or less or 25 linear feet or less of ACM
☐ e. normally non-friable ACM shall be disturbed/removed. Specify amount: _____ square feet
☐ f. ACM will not be disturbed during the scope of work. Specify amount of ACM present: _____ square feet _____ linear feet

All ACM specified in "b", "d", or "e" must be removed in accordance with the DEP Asbestos Rules or NYS DOL ICR56.*

12. RESULTS OF BUILDING SURVEY AND HAZARD ASSESSMENT:

FLOOR (including cellar and basement)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT		ASSUMED ACM
				YES	NO	
5	Apt. 5B	Sheetrock	3		x	

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.

13. Analytical Laboratory Ameri-Sci New York14. ELAP # 11480 15. Date(s) Samples Analyzed 9-12-08

NYS DOH CERTIFICATION

16. I hereby declare the information provided herein is true and complete.

NYC DEP Certified Asbestos Investigator's Signature

106554

Certificate Number

9-12-08


Date

(212) 243-6500

Daytime Telephone Number

Any modification or deviation from information provided on this form must be reported immediately in writing directly to the NYCDEP. The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

* In-plant operations, as defined in §56-3.1 of ICR56, are not permitted in New York City.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATORACP5
2/2001