



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107



ONLY
TYPEWRITTEN
FORMS WILL
BE ACCEPTED

NOT AN ASBESTOS PROJECT

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signature and seal are required. Submittal at the NYCDEP requires one copy of the form with original signature and seal.

2. Facility Address 237 West 10 Street Borough Manhattan Zip 10011
AKA _____ 3. Block 620 4. Lot 37
5. Building Owner 686 Holdings LLC Tel. # (718) 664-6656
6. Address 825 East 233 Street State NY Zip 10466
7. Contact Person Andy Laub 8. Tel. # (718) 664-6656
9. Description of the Entire Scope of Work
Apt. renovations

10. Est. Start Date _____ ☒ As soon as permit approved Est. Completion Date _____ of the Entire Scope of Work.

11. I, Anthony P. Nowicki, Jr., have conducted an asbestos investigation on 11/14/08 in accordance with
Name of Certified Asbestos Investigator Date

Sections 1-16 and 1-27 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☐ a. premise to be demolished is free of any asbestos containing material (ACM).
☐ b. premise to be demolished contains 10 square feet or less or 25 linear feet or less of ACM.
☐ c. cumulative surfaces of structure(s) affected by the work are free of ACM.
☐ d. cumulative surfaces of structure(s) affected by the work contain 10 square feet or less or 25 linear feet or less of ACM
☐ e. normally non-friable ACM shall be disturbed/removed. Specify amount: _____ square feet
☒ f. ACM will not be disturbed during the scope of work. Specify amount of ACM present: TBD square feet TBD linear feet

All ACM specified in "b", "d", or "e" must be removed in accordance with the DEP Asbestos Rules or NYS DOL ICR56.*

12. RESULTS OF BUILDING SURVEY AND HAZARD ASSESSMENT:

FLOOR (including cellar and basement)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT		ASSUMED ACM
				YES	NO	
5th Fl.	Apt. 17	Plaster-Wall/Ceiling	3		☒	

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.

13. Analytical Laboratory Sci Labs

14. ELAP # 11480 15. Date(s) Samples Analyzed 11/15/08

NYS DOH CERTIFICATION

16. I hereby declare the information provided herein is true and complete.

Anthony P. Nowicki, Jr.
NYC DEP Certified Asbestos Investigator's Signature

106554-71609
Certificate Number


11-17-08
Date

106554-71609
Daytime Telephone Number

Any modification or deviation from information provided on this form must be reported immediately in writing directly to the NYCDEP. The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

* In-plant operations, as defined in §56-3.1 of ICR56, are not permitted in New York City.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



ACP5
2/2001