



DEPT BLDGS Job No. 121611988



Scan Code ESHS3792851

EW-MH

EW-MH Non-Directive 14

INSPECTION REPORT

1. TYPE OF INSPECTION: EW-MH Non-Directive 14

2. RECORD INFORMATION

Record Type: DOB/Permit/EW-MH/NA

Record (Job/Permit/Application) #: 12161198801EWMH

Requestor Name: Luz Jaramillo

Requestor Phone Number: 3478013533

3. INSPECTION INFORMATION

Inspection Result: Pass-Final

Inspection Date: 03/15/16 Inspection Time: 09:14 AM

Inspector Badge#: 2693

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments
------------------------	--------	--------------	-----------	----------

5. APPROVAL

Inspection Final Result: Pass-Final

Inspection Final Approval Date: 03/15/16

Inspection Final Approval Time: 06:32 PM

Supervisor Badge #: 2513