



PA

Place of Assembly

INSPECTION REPORT

1. TYPE OF INSPECTION: Place of Assembly

2. RECORD INFORMATION

Record Type: DOB/Job/PA/NA

Record (Job/Permit/Application) #: 121800319

Requestor Name: Satish Patel

Requestor Phone Number:

3. INSPECTION INFORMATION

Inspection Result: Pass-Final

Inspection Date: 02/12/20

Inspection Time:

Inspector Badge#: 2271

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments
------------------------	--------	--------------	-----------	----------

5. APPROVAL

Inspection Final Result: Pass-Final

Inspection Final Approval Date: 02/12/20

Inspection Final Approval Time: 01:57 PM

Supervisor Badge #: 2271

DEPT BLDGS Job No. 121800319



Scan Code ESHS9462722