



PA

Place of Assembly

INSPECTION REPORT

1. TYPE OF INSPECTION: Place of Assembly

2. RECORD INFORMATION

Record Type: DOB/Job/PA/NA

Record (Job/Permit/Application) #: 122100127

Requestor Name: Seay-Yarbrough Inc

Requestor Phone Number: 6467658309

3. INSPECTION INFORMATION

Inspection Result: Pass-Final

Inspection Date: 10/10/19 Inspection Time: 1:59 PM

Inspector Badge#: 3098

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments
------------------------	--------	--------------	-----------	----------

5. APPROVAL

Inspection Final Result: Pass-Final

Inspection Final Approval Date: 10/10/19

Inspection Final Approval Time: 03:47 PM

Supervisor Badge #: 2271