



AL-3

Alt-3 Non-Directive 14

INSPECTION REPORT

1. TYPE OF INSPECTION: Alt-3 Non-Directive 14

2. RECORD INFORMATION

Record Type: DOB/Permit/AL-3/NA

Record (Job/Permit/Application) #: 12338633501ALOT

Requestor Name: CHANG HAHN

Requestor Phone Number: 7189611112

3. INSPECTION INFORMATION

Inspection Result: Pass-Final

Inspection Date: 06/21/18 Inspection Time: 02:04 PM

Inspector Badge#: 2877

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments
------------------------	--------	--------------	-----------	----------

5. APPROVAL

Inspection Final Result: Pass-Final

Inspection Final Approval Date: 06/21/18

Inspection Final Approval Time: 04:07 PM

Supervisor Badge #: 2604