




## NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

## ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) \_\_\_\_\_

Control Number: 1601659

2. Premise No. 250 Street Name Park Avenue Borough Manhattan Zip 101773. AKA \_\_\_\_\_ Type of Facility Commercial BIN 1035405 Block 01282 Lot 0034  
250 Park LLC C/O Cushman4. Building Owner Wakefield Address 250 Park Avenue5. City New York State NY Zip 10177 Contact Person Joseph Politi6. Tel. # (212) 318-9734 Fax # (212) 421-4191 Email JOPE.POLITI@CUSHWAKE.COM

7. Work Type \_\_\_\_\_

## Description of the Entire Scope of Work

HEREWITH FILING TO ADD MECHANICAL EQUIPMENT &amp; DUCT WORK ALONG WITH NEW PLUMBING FIXTURES FOR INCREASED OCCUPANT LOAD ON FLOORS 12,13, AND 14. HERewith FILING FOR PARTITION DEMOLITION AND INSTALLATION RELATED TO INCREASE IN OCCUPANCY LOAD ON 12TH, 13TH AND 14TH FLOORS. MODIFICATIONS TO THE EXISTING FIRE ALARM SYSTEM AS PER PLANS (LL WORK.) NO CHANGE TO USE, EGRESS OR OCCUPANCY.

8. I, MOHAMMAD KARIM, have conducted an asbestos investigation on

Name of Certified Asbestos Investigator

06/22/2019 8:00AM-6:00PM, 06/24/2019 6:00PM-2:00AM

Date(s)

in accordance

with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☒ a. the premises or the portion(s) of the premises, included in the scope of renovations was/were determined that there was no asbestos-containing materials (ACM) present
- ☐ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.  
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
- ☒ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: 33664 sq. ft 879 linear ft.
- ☐ d. entire building is free of asbestos containing material (ACM).



I hereby declare the information provided herein is true and complete

MOHAMMAD KARIM6/26/20191131371/1/2021

DEP Certified Asbestos Investigator's Signature

Date

Certificate Number

Expiration Date

Tel. # (646) 919-6291

Fax # \_\_\_\_\_

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL  
OF THE  
NYC DEP  
CERTIFIED  
ASBESTOS  
INVESTIGATORIs it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No



## NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

## ASBESTOS ASSESSMENT REPORT

RECEIVED

6/26/2019

DEP  
ASBESTOS CONTROL  
PROGRAM

FEE PAID

## 9. RESULTS OF ASBESTOS BUILDING SURVEY:

| Floor              | Section of Floor(s) Surveyed        | Material Assumed to Contain ACM and/or Sampled | Number of Samples Analyzed | Asbestos Present | Assumed ACM | Square Feet | Linear Feet | Abated | Scope of Work Applied |
|--------------------|-------------------------------------|------------------------------------------------|----------------------------|------------------|-------------|-------------|-------------|--------|-----------------------|
| Building Floors-13 | NORTH, SOUTH                        | 2"X2" CEILING TILE                             | 2                          | No               | No          |             |             |        |                       |
| Building Floors-13 | MER NORTH, MER SOUTH                | HVAC DUCT SEALANT                              | 2                          | No               | No          |             |             |        |                       |
| Building Floors-13 | NORTH PERIMETER, SOUTH PERIMETER    | 1X1 CEILING TILE                               | 2                          | No               | No          |             |             |        |                       |
| Building Floors-13 | NORTH, SOUTH                        | GLUE GLOB                                      | 2                          | No               | No          |             |             |        |                       |
| Building Floors-13 | MER NORTH, MER SOUTH                | HVAC JOINT SEALANT                             | 2                          | No               | No          |             |             |        |                       |
| Building Floors-13 | MER NORTHWEST                       | FL TILE & MASTIC                               | 4                          | Yes              | No          | 100         |             | No     | c                     |
| Building Floors-13 | MER NORTHWEST                       | WALL CINDERBLOCK MORTAR                        | 3                          | No               | No          |             |             |        |                       |
| Building Floors-13 | MER NORTHWEST                       | ELBOW INSULATION                               | 3                          | Yes              | No          |             | 15          | No     | c                     |
| Building Floors-13 | MER NORTHWEST                       | ELBOW CANVAS                                   | 2                          | No               | No          |             |             |        |                       |
| Building Floors-13 | WEST AREA, EAST AREA, NORTH AREA    | CEILING PLASTER                                | 15                         | No               | No          |             |             |        |                       |
| Building Floors-13 | NORTH AREA, SOUTH AREA, S WEST AREA | SHEETROCK                                      | 6                          | No               | No          |             |             |        |                       |
| Building Floors-13 | MER SOUTHEAST                       | PIPE ELBOW INSULATION                          | 6                          | No               | No          |             |             |        |                       |
| Building Floors-13 | NW BY FAN ROOM                      | FL TILE AND GLUE TOP, BOTTOM AND MIDDLE        | 12                         | Yes              | No          | 200         |             | No     | c                     |
| Building Floors-13 | BY ELEVATOR, BY BATHROOMS           | WALL PLASTER                                   | 10                         | No               | No          |             |             |        |                       |
| Building Floors-13 | SE WING NORTH OF RECEPTION AREA     | PIPE INSULATION                                | 4                          | Yes              | No          |             | 24          | No     | c                     |
| Building Floors-13 | NORTHWEST ROOM, SOUTHWEST ROOM      | FL CARPET GLUE                                 | 2                          | No               | No          |             |             |        |                       |

I hereby declare the information provided herein is true and complete

MOHAMMAD KARIM   
DEP Certified Asbestos Investigator's Signature6/26/2019  
Date113137  
Certificate Number1/1/2021  
Expiration Date

Tel. # (646) 919-6291 Fax #

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL  
OF THE  
NYC DEP  
CERTIFIED  
ASBESTOS  
INVESTIGATORIs it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No

25615589




**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION**  
**Asbestos Control Program**  
 59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



|                    |                                                              |                                                                |    |     |    |       |    |    |   |
|--------------------|--------------------------------------------------------------|----------------------------------------------------------------|----|-----|----|-------|----|----|---|
| Building Floors-13 | PERIMETER                                                    | FL LEVELING                                                    | 3  | No  | No |       |    |    |   |
| Building Floors-13 | PERIMETER WEST, PERIMETER SOUTH                              | FL TILE & GLUE                                                 | 4  | Yes | No | 12000 |    | No | c |
| Building Floors-13 | EAST ROOM BY RECEPTION AREA                                  | BLACK MASTIC                                                   | 2  | No  | No |       |    |    |   |
| Building Floors-13 | EAST ROOM BY RECEPTION                                       | FL TILE & MASTIC                                               | 4  | Yes | No | 200   |    | No | c |
| Building Floors-13 | NORTH MIDDLE ROOM                                            | FL TILE & MASTIC 1ST LAYER, 2ND LAYER, 3RD LAYER AND 4TH LAYER | 16 | Yes | No | 200   |    | No | c |
| Building Floors-13 | NORTH EAST ROOM                                              | FL TILE & MASTIC                                               | 4  | Yes | No | 200   |    | No | c |
| Building Floors-14 | WEST MIDDLE ROOM, SOUTH WEST PRINTER ROOM                    | 12"X12" FLOOR TILE & GLUE                                      | 4  | No  | No |       |    |    |   |
| Building Floors-14 | WEST MIDDLE CORRIDOR, EAST MIDDLE CORRIDOR                   | 12"X12" CEILING TILE                                           | 2  | No  | No |       |    |    |   |
| Building Floors-14 | WEST CORRIDOR, EAST CORRIDOR                                 | CEILING TILE GLUE GLOB                                         | 2  | No  | No |       |    |    |   |
| Building Floors-14 | WEST MIDDLE, SOUTHEAST                                       | 24"X24" CEILING TILE                                           | 2  | No  | No |       |    |    |   |
| Building Floors-14 | WEST MIDDLE ROOM                                             | FLOOR PAINT TEXTURE                                            | 2  | No  | No |       |    |    |   |
| Building Floors-14 | WEST MIDDLE ROOM                                             | PIPE INSULATION COLUMN                                         | 3  | Yes | No |       | 24 | No | c |
| Building Floors-14 | WEST CORRIDOR, SOUTHWEST CORRIDOR                            | SOFFIT PLASTER                                                 | 3  | No  | No |       |    |    |   |
| Building Floors-14 | SOUTHWEST OFFICE, NORTH OFFICE                               | COVE BASE AND GLUE                                             | 4  | No  | No |       |    |    |   |
| Building Floors-14 | SOUTHWEST, WEST, NORTHWEST, NORTH, MIDDLE NORTH, EAST, SOUTH | WALL PLASTER                                                   | 14 | No  | No |       |    |    |   |
| Building Floors-14 | WEST, SOUTH                                                  | HVAC DUCT SEALANT                                              | 2  | No  | No |       |    |    |   |


**I hereby declare the information provided herein is true and complete**

MOHAMMAD KARIM  6/26/2019 113137 1/1/2021  
 DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (646) 919-6291 Fax # \_\_\_\_\_

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No





# NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

## ASBESTOS ASSESSMENT REPORT



|                    |                                                                                            |                           |    |     |    |       |     |    |   |
|--------------------|--------------------------------------------------------------------------------------------|---------------------------|----|-----|----|-------|-----|----|---|
| Building Floors-14 | WEST CORRIDOR, EAST CORRIDOR, SOUTH CORRIDOR                                               | CEILING PLASTER           | 14 | No  | No |       |     |    |   |
| Building Floors-14 | SOUTH CORRIDOR, WEST CORRIDOR, NORTH CORRIDOR, SOUTH CORRIDOR, NW CORRIDOR, EAST CORRIDOR, | SHEETROCK WALL            | 8  | No  | No |       |     |    |   |
| Building Floors-14 | WEST MIDDLE                                                                                | CINDERBLOCK MORTAR        | 3  | No  | No |       |     |    |   |
| Building Floors-14 | WEST MIDDLE                                                                                | WALL PATCHING             | 3  | No  | No |       |     |    |   |
| Building Floors-14 | WEST MIDDLE ROOM, WEST, SOUTH ROOM                                                         | FLOOR TILE AND GLUE       | 8  | Yes | No | 12000 |     | No | c |
| Building Floors-14 | WEST ROOM, SOUTH ROOM                                                                      | FLOOR CARPET GLUE         | 2  | No  | No |       |     |    |   |
| Building Floors-14 | WEST, SOUTH WEST, SOUTH                                                                    | FLOOR LEVELING            | 6  | No  | No |       |     |    |   |
| Building Floors-14 | WEST CORRIDOR                                                                              | PIPE INSULATION           | 2  | Yes | No |       | 120 | No | c |
| Building Floors-14 | WEST CORRIDOR                                                                              | ELBOW INSULATION          | 2  | Yes | No |       | 24  | No | c |
| Building Floors-14 | WEST MIDDLE ROOM                                                                           | PIPE CANVAS               | 2  | No  | No |       |     |    |   |
| Building Floors-14 | EAST MER                                                                                   | DUCT INSULATION           | 3  | Yes | No | 120   |     | No | c |
| Building Floors-14 | EAST MER                                                                                   | HVAC DUCT INSULATION SEAM | 3  | Yes | No | 120   |     | No | c |
| Building Floors-14 | EAST MER                                                                                   | FALLEN DUCT INSULATION    | 2  | Yes | No | 10    |     | No | c |
| Building Floors-14 | EAST MER                                                                                   | ELBOW AND FITTING TAR     | 4  | Yes | No | 10    |     | No | c |
| Building Floors-14 | EAST MER                                                                                   | WALL CINDERBLOCK MORTAR   | 3  | No  | No |       |     |    |   |
| Building Floors-14 | EAST, SOUTHEAST, SOUTH MIDDLE, SOUTH WEST, WEST, NW                                        | WALL JOINT COMPOUND       | 7  | No  | No |       |     |    |   |


I hereby declare the information provided herein is true and complete

MOHAMMAD KARIM MZ 6/26/2019 113137 1/1/2021  
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (646) 919-6291 Fax #

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # ☒ No



25615589

**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION**

Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**

RECEIVED

6/26/2019

DEP  
ASBESTOS CONTROL  
PROGRAM

FEE PAID

|                    |                                 |                              |    |    |    |  |  |  |  |
|--------------------|---------------------------------|------------------------------|----|----|----|--|--|--|--|
| Building Floors-14 | NORTHEAST MER                   | DUCT JOINT SEALANT           | 2  | No | No |  |  |  |  |
| Building Floors-14 | WEST MIDDLE                     | HANGER INSULATION            | 3  | No | No |  |  |  |  |
| Building Floors-14 | NORTH CONFERENCE ROOM           | WALL PAPER AND GLUE          | 4  | No | No |  |  |  |  |
| Building Floors-14 | EAST MIDDLE, NORTH              | COVE BASE AND GLUE           | 4  | No | No |  |  |  |  |
| Building Floors-14 | SOUTHWEST, NORTH                | CARPET GLUE AND BLACK MASTIC | 4  | No | No |  |  |  |  |
| Building Floors-12 | SOUTHWEST ROOMS                 | FL BLACK MASTIC              | 2  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH WEST ROOM, SOUTH CORRIDOR | FLOOR CARPET GLUE            | 2  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH CORRIDOR, NORTHWEST       | COVEBASE & GLUE              | 4  | No | No |  |  |  |  |
| Building Floors-12 | SOUTHWEST MER                   | VALUE INSULATION             | 1  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH WEST MER                  | VALUE CANVAS                 | 2  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH WEST MER, NORTH EAST MER  | HVAC DUCT SEALANT            | 2  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH EAST MER                  | FL PAINT TEXTURED            | 2  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH WEST MER                  | FIRE STOPPER                 | 2  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH WEST MER                  | FL BLACK MASTIC              | 4  | No | No |  |  |  |  |
| Building Floors-12 | SOUTH WEST                      | COVE BASE & GLUE             | 4  | No | No |  |  |  |  |
| Building Floors-12 | BY ELEVATOR, BY STAIRS          | CEILING PLASTER              | 14 | No | No |  |  |  |  |
| Building Floors-12 | NORTH EAST ROOM                 | CEILING GLUE GLOB            | 2  | No | No |  |  |  |  |
| Building Floors-12 | NORTH EAST ROOM                 | 12"X12" CEILING TILE         | 2  | No | No |  |  |  |  |
| Building Floors-12 | NORTH EAST MER                  | WALL CINDERBLOCK MORTAR      | 3  | No | No |  |  |  |  |

**I hereby declare the information provided herein is true and complete**

MOHAMMAD KARIM

6/26/2019

113137

1/1/2021

DEP Certified Asbestos Investigator's Signature

Date

Certificate Number

Expiration Date

Tel. # (646) 919-6291

Fax #

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL  
OF THE  
NYC DEP  
CERTIFIED  
ASBESTOS  
INVESTIGATORIs it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No

25615589



## NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

## ASBESTOS ASSESSMENT REPORT

RECEIVED

6/26/2019

DEP  
ASBESTOS CONTROL  
PROGRAM

FEE PAID

|                    |                                                              |                      |    |     |     |  |     |    |   |
|--------------------|--------------------------------------------------------------|----------------------|----|-----|-----|--|-----|----|---|
| Building Floors-12 | SOUTH WEST, NORTH WEST                                       | 24"X24" CEILING TILE | 2  | No  | No  |  |     |    |   |
| Building Floors-12 | NORTH EAST, NORTH WEST, SOUTH EAST, SOUTH WEST, NORTH, SOUTH | WALL SHEETROCK       | 7  | No  | No  |  |     |    |   |
| Building Floors-12 | NORTH EAST, NORTH WEST, SOUTH EAST, SOUTH WEST, NORTH, SOUTH | WALL JOINT COMPOUND  | 7  | No  | No  |  |     |    |   |
| Building Floors-12 | CORRIDOR BY STAIR E                                          | WALL PAPER GLUE      | 2  | No  | No  |  |     |    |   |
| Building Floors-12 | NORTH, SOUTH                                                 | COVE BASE & GLUE     | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | NORTH EAST                                                   | FL TILE AND MASTIC   | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | NORTH MECHANICAL ROOM AREA                                   | FL TILE AND MASTIC   | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | ADJACENT TO PE ELEVATOR                                      | FL TILE AND MASTIC   | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | ADJACENT TO ELEVATOR, BY ELEVATOR, SOUTH WEST MECH ROOM      | WALL PLASTER         | 14 | No  | No  |  |     |    |   |
| Building Floors-12 | CORRIDOR BY CONFERENCE ROOM                                  | FL LEVELING          | 3  | No  | No  |  |     |    |   |
| Building Floors-12 | SOUTH WEST                                                   | FL COVERING          | 2  | No  | No  |  |     |    |   |
| Building Floors-12 | NORTH EAST ROOM                                              | FL TILE AND MASTIC   | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | PANTRY                                                       | FL TILE AND MASTIC   | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | SOUTH WEST MIDDLE                                            | FL TILE AND MASTIC   | 4  | No  | No  |  |     |    |   |
| Building Floors-12 | CORRIDOR BY STAIR E                                          | FL COVERING          | 2  | No  | No  |  |     |    |   |
| Building Floors-13 | BATHROOM                                                     | WET COLUMNS          | 0  | Yes | Yes |  | 120 | No | c |

I hereby declare the information provided herein is true and complete


MOHAMMAD KARIM  6/26/2019 113137 1/1/2021  
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (646) 919-6291 Fax #

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL  
OF THE  
NYC DEP  
CERTIFIED  
ASBESTOS  
INVESTIGATOR

Is it a Build-It-Back project? ☐ Yes, App ID # ☒ No

25615589




**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION**  
**Asbestos Control Program**  
 59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



|                    |                                              |                               |   |     |     |      |     |    |   |
|--------------------|----------------------------------------------|-------------------------------|---|-----|-----|------|-----|----|---|
| Building Floors-13 | BATHROOM                                     | HIDDEN PIPE                   | 0 | Yes | Yes |      | 24  | No | c |
| Building Floors-13 | BATHROOM                                     | WALL AND FL GLUE              | 0 | Yes | Yes | 1200 |     | No | c |
| Building Floors-13 | BATHROOM                                     | MIRROR GLUE                   | 0 | Yes | Yes | 10   |     | No | c |
| Building Floors-13 | PERIMETER                                    | WALL TAR                      | 0 | Yes | Yes |      | 120 | No | c |
| Building Floors-13 | PERIMETER                                    | RADIATOR ELBOW OR SEALANT     | 0 | Yes | Yes |      | 120 | No | c |
| Building Floors-13 | COLUMN                                       | FIREPROOFING                  | 0 | Yes | Yes | 1800 |     | No | c |
| Building Floors-13 | UNDER FLOOR                                  | CERAMIC TILE SUSPECT MATERIAL | 0 | Yes | Yes | 120  |     | No | c |
| Building Floors-14 | WET COLUMNS                                  | PIPE INSULATION               | 0 | Yes | Yes |      | 120 | No | c |
| Building Floors-14 | BATHROOMS                                    | PIPE CHASES                   | 0 | Yes | Yes |      | 24  | No | c |
| Building Floors-14 | BATHROOM                                     | WALL AND FLOOR GLUE           | 0 | Yes | Yes | 1200 |     | No | c |
| Building Floors-14 | BATHROOM                                     | MIRROR GLUE                   | 0 | Yes | Yes | 10   |     | No | c |
| Building Floors-13 | EAST AREA, WEST AREA, SOUTH AREA, NORTH AREA | JOINT COMPOUND                | 7 | No  | No  |      |     |    |   |
| Building Floors-13 | MER SOUTH EAST                               | CANVAS ELBOWS 6"              | 2 | No  | No  |      |     |    |   |
| Building Floors-13 | BY FREIGHT                                   | WALL PLASTER                  | 4 | No  | No  |      |     |    |   |
| Building Floors-13 | PANTRY                                       | FL TILE AND MASTIC            | 4 | No  | No  |      |     |    |   |
| Building Floors-14 | WEST MIDDLE ROOM                             | ELBOW INSULATION              | 2 | No  | No  |      |     |    |   |
| Building Floors-12 | PERIMETER                                    | WET COLUMN                    | 0 | Yes | Yes |      | 120 | No | c |
| Building Floors-12 | BATHROOM                                     | HIDDEN PIPE                   | 0 | Yes | Yes |      | 24  | No | c |


I hereby declare the information provided herein is true and complete

MOHAMMAD KARIM  6/26/2019 113137 1/1/2021  
 DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (646) 919-6291 Fax # \_\_\_\_\_

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No



25615589



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



|                    |           |                        |   |     |     |      |  |    |   |
|--------------------|-----------|------------------------|---|-----|-----|------|--|----|---|
| Building Floors-12 | BATHROOM  | WALL CERAMIC TILE GLUE | 0 | Yes | Yes | 1200 |  | No | c |
| Building Floors-12 | BATHROOM  | FL WATERPROOFING       | 0 | Yes | Yes | 400  |  | No | c |
| Building Floors-12 | PERIMETER | WALL TAR               | 0 | Yes | Yes | 1200 |  | No | c |
| Building Floors-12 | PERIMETER | RADIATOR HOSE GLUE     | 0 | Yes | Yes | 10   |  | No | c |
| Building Floors-12 | STAIRWELL | FIRE DOOR INSULATION   | 0 | Yes | Yes | 48   |  | No | c |
| Building Floors-12 | COLUMN    | FIREPROOFING           | 0 | Yes | Yes | 1200 |  | No | c |
| Building Floors-12 | BATHROOM  | MIRROR GLUE            | 0 | Yes | Yes | 10   |  | No | c |
| Building Floors-13 | STAIRWELL | FIRE DOOR INSULATION   | 0 | Yes | Yes | 48   |  | No | c |
| Building Floors-14 | STAIRWELL | FIRE DOOR INSULATION   | 0 | Yes | Yes | 48   |  | No | c |

10. ANALYTICAL LABORATORY:

| NAME                | ELAP # (NYS DOH CERTIFICATION) | DATE(S) SAMPLES ANALYZED |
|---------------------|--------------------------------|--------------------------|
| Atlas Environmental | 11999                          | 6/24/2019                |
| Atlas Environmental | 11999                          | 6/25/2019                |

11. NYS DOL Asbestos Handling license # 29705 Company Name Consulting And Testing Services, Inc.

12. Comment

DRAWINGS BY: DPM ARCHITECTURE P.C DATED:03/29/2019

CTSI#16140-19

I hereby declare the information provided herein is true and complete

MOHAMMAD KARIM 6/26/2019 113137 1/1/2021  
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (646) 919-6291 Fax #

Email mohammadk@ctsiweb.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL OF THE  
NYC DEP  
CERTIFIED  
ASBESTOS  
INVESTIGATOR



Is it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No



25615589