



PW7:
Letter of Completion Request

(Form must be typewritten)

1 LOCATION INFORMATION

House No(s) 62 Street Name WEST TREMONT AVENUE Work Proposed on Floor No(s) BAS

Borough BRONX Block 2862 Lot 8 BIN 2008383 CB No. 205

2 REQUESTOR INFORMATION

Individual's Relationship to Job (i.e., Applicant, Owner Filing Representative) FILING REPRESENTATIVE

Last Name OCASIO First Name BERNIE Middle Initial
Business Name BETRO EXPEDITING SERVICES Business Telephone (212) 481-7448
Business Address 119-17 29TH AVENUE Business Fax
City FLUSHING State NY Zip 11354 Mobile Telephone
Email BERNIE@BETRODESIGN.COM License No. A10412

3 TYPE OF REQUEST

- ☒ Letter of Completion (Directive 14 or Non-Directive 14)
- ☐ Notification of removal of chute, fence, supported scaffold, sidewalk shed, temporary hoist, support of excavation, or other temporary construction equipment. No final inspection is required per LL146/21.

4 STATEMENTS & SIGNATURES

By signing below, I understand that all the information provided is true to the best of my knowledge and that falsification of any statement is a misdemeanor under § 28-320.6.3 of the NYC Administrative Building Code and punishable by a fine or imprisonment, or both. It is unlawful to give to a City employee, or for a City employee to accept, any benefit, monetary or otherwise, either as a gratuity for properly performing the job or in exchange for special consideration. Violation is punishable by imprisonment or fine, or both.

Requestor's Signature: Bernard Ocasio

Date: 12-04-2023

FOR OFFICE USE ONLY

DISAPPROVAL REASONS

Review request cannot be processed for the following reasons:

- ☐ Fees unpaid ☐ Open ECB/DOB Violation(s) ☐ Incomplete PAA ☐ Audit Conditions Pending/Job on
- ☐ Missing inspection Sign-off(s): ☐ Construction ☐ Plumbing ☐ Electrical ☐ Other: _____
- ☐ Missing Required Item(s): _____ TR1 Error(s): _____
- ☐ Form(s) Missing/Incomplete: Form(s) _____ Section(s)/Reason(s): _____
- ☐ Other: _____