



PA

Place of Assembly

INSPECTION REPORT

1. TYPE OF INSPECTION: Place of Assembly

2. RECORD INFORMATION

Record Type: DOB/Job/PA/NA

Record (Job/Permit/Application) #: 220644578

Requestor Name: Joseph Rivera

Requestor Phone Number:

3. INSPECTION INFORMATION

Inspection Result: Pass-Final

Inspection Date: 09/23/20

Inspection Time:

Inspector Badge#: 2604

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments

5. APPROVAL

Inspection Final Result: Pass-Final

Inspection Final Approval Date: 09/23/20

Inspection Final Approval Time: 09:01 AM

Supervisor Badge #: 2604