

C.E. BOSS CO., INC.

INSPECTION • TESTING • ENGINEERS

3319 MERRITT AVENUE • BRONX, NY 10475 • (718) 994-3200 • FAX (718) 994-5406

CONCRETE CYLINDER TEST REPORT

REPORT No.:

1CC

DATE:

December 5, 2001

CLIENT: Robert Florio

PROJECT: FLORIO RESIDENCE @ 112 BAY 34TH STREET - BROOKLYN, NY

CONTRACTOR: -----

SUPPLIER: -----

CAST BY: -----

REQUIRED STRENGTH: -----

DELIVERED BY: CEBCO (11/08/01)

SAMPLE DATA

LAB No.	4229	4230	4228	4226	4227	4228
SAMPLE No.	1	2	3	4	5	6
DATE PLACED	10/22/01					
DATE TESTED	11/19/00					
AGE @ TEST	28 Days					
SLUMP (in.)	-----					
AIR (%)	-----					
CYL. WGT. (lb.)	25.3	26.8	28.0	28.0	27.9	26.4
CONC. TEMP. (°F)	-----					
TRUCK No.	-----					
TIME	-----					
DIAMETER (in.)	6.0					
AREA (in. ²)	28.27					
STRENGTH (psi)	2993	3104	2741	3554	3396	2844

SAMPLE No.

SAMPLE LOCATION

1 - 6 None Indicated

NOTE: Data not repeated is typical for all samples tested, unless otherwise noted. All data regarding dates and locations supplied by Contractors.

REMARKS:

Respectfully submitted,

C.E. Boss Co., Inc.

Jack W. Mandelson, PE

JWM:lab

NEW YORK CITY, DEPARTMENT OF BUILDINGS, CONCRETE TESTING LABORATORY: LICENSE #44.

Cc: 2-Client, 1-Billing

CONCRETE • STEEL • SOIL • MASONRY • ENVIRONMENTAL • TEST BORINGS • GEOTECHNICAL • CONSTRUCTION

421/08
Florio Residence 112 Bay 34TH Street - 14th. Cylinders