



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program

59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107**NOT AN ASBESTOS PROJECT**ONLY
TYPEWRITTEN
FORMS WILL
BE ACCEPTED

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signature and seal are required. Submittal at the NYCDEP requires one copy of the form with original signature and seal.

2. Facility Address 7523 Third Avenue Borough Brooklyn Zip 11209
AKA _____ 3. Block 5940 4. Lot 1
5. Building Owner Tanoreen Caterers Tel. # 718-748-5600
6. Address 7523 3rd Avenue State NY Zip 11209
7. Contact Person Rawia Bishara 8. Tel. # 718-748-5600
9. Description of the Entire Scope of Work
INSTALL FIRE SUPPRESSION SYSTEM WITHIN EXISTING STAINLESS STEEL RANGEHOOD TO COMPLY WITH CURRENT FIRE DEPARTMENT RULES AND REGULATIONS.

10. Est. Start Date _____ ☒ As soon as permit approved Est. Completion Date 12/1/09 of the Entire Scope of Work.11. I, V. AZHAZHA, have conducted an asbestos investigation on 3/5/09 in accordance with
Name of Certified Asbestos Investigator Date

Sections 1-16 and 1-27 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☐ a. premise to be demolished is free of any asbestos containing material (ACM).
☐ b. premise to be demolished contains 10 square feet or less or 25 linear feet or less of ACM.
☒ c. cumulative surfaces of structure(s) affected by the work are free of ACM.
☐ d. cumulative surfaces of structure(s) affected by the work contain 10 square feet or less or 25 linear feet or less of ACM
☐ e. normally non-friable ACM shall be disturbed/removed. Specify amount: _____ square feet
☐ f. ACM will not be disturbed during the scope of work. Specify amount of ACM present: _____ square feet _____ linear feet

All ACM specified in "b", "d", or "e" must be removed in accordance with the DEP Asbestos Rules or NYS DOL ICR56.*

12. RESULTS OF BUILDING SURVEY AND HAZARD ASSESSMENT:

FLOOR (including cellar and basement)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT YES NO	ASSUMED ACM
1	KITCHEN WITHIN EXISTING	NONE DONE	None		✓
	STAINLESS STEEL RANGEHOOD				


13. Analytical Laboratory N/A14. ELAP # N/A 15. Date(s) Samples Analyzed N/A

16. I hereby declare the information provided herein is true and complete.

NYC DEP Certified Asbestos Investigator's Signature 105619 3/5/09 (917) 519-1489
Certificate Number Date Daytime Telephone Number

Any modification or deviation from information provided on this form must be reported immediately in writing directly to the NYCDEP. The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

* In-plant operations, as defined in §56-3.1 of ICR56, are not permitted in New York City.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATORACP5
2/2001