



**Environmental
Protection**

Carter H. Strickland, Jr.
Commissioner

James J. Roberts, P.E.
Deputy Commissioner
**Bureau of Water &
Sewer Operations**
jroberts@dep.nyc.gov

59-17 Junction Boulevard
Flushing, NY 11373

January 24, 2013

BTE Design Services
172-13 Hillside Avenue, Suite # 201
Jamaica, New York 11432
Attn: Yun Zhen Zeng-Posner

To Whom It May Concern:

The hydrant flow test you requested in the vicinity of **315 Franklin Avenue, Brooklyn** was performed on **1/16/2013** at **11:30 AM** the following results:

The static pressure taken on the west side of Franklin Avenue 1st hydrant south of Lafayette Avenue was 45 pounds per square inch. The residual pressure at this point was 44 pounds per square inch when 500 gallons of water per minute were flowing from the west side of Franklin Avenue 1st hydrant south of Clifton Place.

This Department cannot guarantee that this pressure will be maintained in the future because a change may be needed in conformity with good engineering practices.

The flow test was performed on a 12 inch water main, which is fed from one direction.

If you have any questions on the above, please contact me at (718) 595-7135, fax at (718) 595-7408.

Very truly yours,

Urszula Krajewski, P.E.
Water Distribution Engineer
City Wide Hydraulic Testing Unit

File: FT2012-2280-L24-0092

All hydrant flow test requests are to be addressed to: NYCDEP-BWSO; 59-17 Junction Blvd, 12th Fl., Flushing, NY 11373-5108, Attn: Citywide Hydraulic Flow Test Unit

Enclose payment for \$500 payable to NYC Water Board for each test. Indicate the test street, cross streets and borough for each test. All requests are to be made by US or overnight mail, no hand deliveries accepted.