




NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) _____ **Control Number: 3062464**
2. Premise No. 6305 Street Name Avenue N Borough Brooklyn Zip 11234
3. AKA _____ Type of Facility Commercial BIN 3235909 Block 08363 Lot 0008
4. Building Owner Michael Serrapica Address 6305 Avenue N
5. City Brooklyn State NY Zip 11234 Contact Person Mr. Liu
6. Tel. # (917) 515-1022 Fax # _____ Email _____
7. Description of the Entire Scope of Work
alteration of existing commercial space to a restaurant, minor change of partitions, wall, floor, counter, plumbing fixtures and store front to be installed.

8. I, DING-YEU CHEN, have conducted an asbestos investigation on
Name of Certified Asbestos Investigator

02/23/2013 _____ in accordance
Date(s)


with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☒ a. portion(s) of the premises affected by the work is free of asbestos containing material (ACM).
- ☐ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
- ☐ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: _____ sq. ft. _____ linear ft.
Specify locations (attach additional documents as necessary): _____

- ☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

FLOOR	DESCRIBE SECTION OF FLOOR	ALL MATERIALS ASSUMED TO CONTAIN ACM AND/OR SAMPLED	NUMBER OF SAMPLES ANALYZED	ASBESTOS PRESENT	ASSUMED ACM
first floor	store wall	gypsum boards (homogenous)	3	No	No
first floor	store - floor (entire)	carpet on the plywood (subfloor) - photos are taken of existing condition at the time of inspection.	0	No	No
first floor	ceiling (homogenous)	existing ceiling boards to be kept (photos are taken of existing condition)	0	No	No


I hereby declare the information provided herein is true and complete

DING-YEU CHEN 2/25/2013 119258 11/24/2014
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (917) 681-7078 Fax # _____ Email chiefeddie1@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR





NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



cellar	storage	concrete slab and concrete foundation wall (photos are taken of existing condition)	0	No	No
--------	---------	---	---	----	----

10. ANALYTICAL LABORATORY:

NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
New York Environmental and Lab.	11510	2/25/2013


11. NYS DOL Asbestos Handling license # 63014 Company Name Sigma Building Services, Inc.

I hereby declare the information provided herein is true and complete

DING-YEU CHEN 2/25/2013 119258 11/24/2014
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (917) 681-7078 Fax # Email chiefeddie1@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

SEAL
OF THE
NYC DEP
CERTIFIED
ASBESTOS
INVESTIGATOR



2565728