



AL-1

CO-Alt-1 Inspection Up to 4 Total Levels

INSPECTION REPORT

1. TYPE OF INSPECTION: CO-Alt-1 Inspection Up to 4 Total Levels

2. RECORD INFORMATION

Record Type: DOB/Permit/AL-1/NA

Record (Job/Permit/Application) #: 32154742001AL

Requestor Name: City Building NY Architect P.C.

Requestor Phone Number: 9178039511

3. INSPECTION INFORMATION

Inspection Result: Fail-Final

Inspection Date: 06/07/19 Inspection Time: 3:20 PM

Inspector Badge#: 2737

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments
Other (describe)	Local Requirements Not Met	Yes	ALL	s/o the alt 2 in conjunction with the alt 1/s/o the s o e and the sprinkler applications

5. APPROVAL

Inspection Final Result: Fail-Final

Inspection Final Approval Date: 06/07/19

Inspection Final Approval Time: 03:45 PM

Supervisor Badge #: 1732