

NYC Department of Buildings

Electrical Application Details for App #: B401902

Premises: 2111 EAST 68 STREET BROOKLYN

BIN: [3237584](#) Block: 8428 Lot: 33

Application Completed and Certified

Filed: 2111 E 68 ST
7795675
BROOKLYN, NY 11234

Census Tract: 706
Admin Area: B - BROOKLYN
Community Board: 318

Health Area: 8822
Inspection Area: Q

DOB Cross Street(s): AVENUE U, EAST MILL BASIN SHORELINE

Status: C - JOB IS SIGNED OFF 11/24/2015

Request Type: A - APPLICATION

eFiled: YES

Permit Issued: 10/07/2015 4:17 PM

Application Entered: 10/07/2015

Job Start Date: 10/17/2015

Last Change: 11/24/2015

Job End Date: 10/18/2015

Appointment Status:

Last Inspection By: CAMPBELL, C On 11/19/2015

Field Disp: C - INSPECTION PASSED

Energize Recommendation:

Objection Disposition:

License #: [012354](#)
Firm: [004140](#)
Firm Phone: 718-892-2985

Licensee Name: JOSEPH A SPIRELLI
Firm Name: SPIRELLI ELECTRIC INC
Firm Address: 1901 AMETHYST STREET BRONX NY 10462

Work Started or Filed by Others: NO

Work Category: R - REHABILITATION

Work To Be Done:
E - SUSTAINABLE ENERGY - SOLAR

Total Fee: \$100.00

Other Work:

Work Related to a New or Amended Certificate of Occupancy: NO

This Job Regulated by the NYC Energy Conservation Code: No

Building Used As: C - Three Family

Special Cert Approval:

Advisory Board Approval: NOT APPLICABLE

Owner / Occup: JANE RICHMOND
2111 E 68 ST BROOKLYN NY 11234

Authorized Representative:

Relationship To Owner:

WORK DESCRIPTION

BUILDING OVERVIEW		Are Feeders Being Installed? : Yes	
(If feeders are being installed, provide a wiring diagram and calculations at the time of inspection)			
Building Overview Work Items		QUANTITY	DESCRIPTION
SERVICE SWITCHES			
A. Up to 100 AMPS		0	
B. 101 Up to 200 AMPS		0	
C. 201 Up to 600 AMPS		0	
D. 601 Up to 1200 AMPS		0	
E. Over 1200 AMPS		0	
SER. ENT. & FDR COND (EACH SET)			
A. Up to #2 CONDUCTOR		4	3@10, 1@8
B. Over #2 to 1/0		0	
C. Over 1/0 to 250 MCM		0	
D. Over 250 MCM		0	
PANELS			
A. 1 Phase Up to 20-1 or 10-2 Pole Brkrs		0	
B. 1 Phase Over to 21-1 or 10-2 Pole Brkrs		0	
C. 3 Phase Up to 225 AMPS		0	
D. 3 Phase Over 225 AMPS		0	
ELEVATORS / ESCALATORS / MATERIAL LIFTS			
A. Total No. of Elevators / Escalators / Material Lifts		0	
B. Each Additional 10 Floors Or Less		0	
BOILER CONTROLS		0	

FLOOR DESCRIPTIONS

Floor	Apt.	Number Of Outlets				No. Of Fixtures	Motors / Generators		Heaters		Transformers	
		Fixt	Receptacles		Switch		Num	Total HP KW	Num	Total KW	Num	Total KVA
			ATT	A/C								
Buildings Total												
Total Units : 0 units												

Signs: Field Connect: 0 Field Inspect: 0 Tags:

SERVICE / METER EQUIPMENT

Meter Request to Utility		#3-Wire	0	#4-Wire	0	#10-Wire	0
Existing Meters	0	+ New Meters	0	- Removed Meters	0	= Total Meters	0

Power Auth Flag:

Power Requested:

Power Issued:

Objection Flag:

Notice:

Response:

Follow-Up: K - (CLOSED)

Contractor's Comments:

INSPECTION FOR APPLICATION #: B401902

INSP ID	FIELD DATE	DISP DATE	INSP ID	FLD DISP	OBJ DISP	ENRG REC	TIME INSP	REINSP DATE	NEW OBJ	APPT FLAG
(1)	11/02/2015	11/10/2015	WYF	Z			(0)		(0)	Y
INSPECTION COMMENTS:			CONTRACTOR CANCELLED WITH OFFICE							
(2)	11/19/2015	11/24/2015	CLC	C			(15)		(0)	Y
INSPECTION COMMENTS:			N							

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.