



TECHNICAL REVIEW (FOR ZRD1 AND CCD1) REJECTION FORM



1 Location Information:

House # 15-71 Street Name: 208 ST
 Determination Process Tracking # ALT-2 disappr DOB# 420031913
 Borough # QUEENS Block 5860 Lot 42 BIN .

2 Applicant Information:

Last Name: Montag First Name: Arnold
 Fax # 516-829-7946

3 Summary Review:

Submission for determination request has been reviewed by the Technical Expert and found the request is incomplete and is rejected due to the following reason(s):

Lack of supporting documentation:

- | | | | |
|--|--|--|--|
| ☐ Sanborn map(s) | ☐ Tax map(s) | ☐ Easement/declaration(s) | ☒ Plan(s)/sketch |
| ☐ Records | ☐ Survey(s) | ☐ Photo(s) | ☐ C of O |
| ☐ Objection Sheet | ☐ Other (explain) _____ | | |

4 Comment(s):

If request is based on a plan examiner objection, type it exactly as it appears on the objection sheet & provide copy of the objection sheet.

Provide plans/sketches and other relevant documentation in connection with your request.

An appointment will be scheduled with Simon Lee, bring required documentation.

* to be resolved by plan examiner
plans show First Floor level, with partial
cellar level. the work is limited to
First Floor kitchen Area

REQUIRED DOCUMENTS MUST NOT BE LARGER THAN 11" X17" IN SIZE.

Use tracking # for resubmission to prevent delays.

Simon Lee
12/17/09