

Expedite-Dem Inc
99 Darcey Ave
Staten Island, NY 10314
718-477-4444
Flory, Lilia, Viv

NYC **BUILDINGS**

CB 402

**APPLICATION FOR INSPECTION PRIOR
(AND PRE-DEMOLITION REF)**


Application must be typewritten.

DEPT. BLDGS. 420289057 Job Number
SC100219003 Scan Code

Applicant, please complete all information requested below: (For mechanical demolition requests complete form BEST-4 as well.)

Number of structures at this address you intend to demolish (a separate application is required for each):
Name: Peter Neofytides Company: Mac-Hudson Corp
E-mail: Phone: 718-482-8400 Fax:
Application date: 11/18/10 ☐ Bronx ☐ Brooklyn ☐ Manhattan ☒ Queens ☐ Staten Island
Structure type (check only one): ☐ House ☐ Garage ☐ Shed ☒ Commercial Building ☐ Other:
Building address: 10-02 44 Drive, Queens NY 11101 Legalizing a completed demolition? ☐ Yes ☒ No
Cross streets: 10 ST & 11 ST BIN: 4000435 Block: 51 Lot: 42
All AKA's ("Also-Known-As", if applicable): 44-57/71 10 ST
BIS job # for demolition (DM) filing: 420289057 Other related BIS job #s (if applicable):
Distance from nearest street corner (in feet): 0' Mechanical demolition requested? ☐ No ☒ Full ☐ Partial
BEST must be notified in writing 24 hours prior to the commencement of any demolition (see AC §27-195).

PLOT DIAGRAM (MUST INDICATE ZONE OF SAFETY ON DIAGRAM)



The north point of the diagram
must agree with the arrow

A survey may be submitted in addition to or in lieu of a plot diagram as long as the zone of safety is indicated.

DO NOT WRITE BELOW THIS LINE: OFFICIAL USE ONLY

Date of report: 1-18-11 Number of stories: 1 Height of building: 20'
Occupancy: Is building vacant? ☒ Yes ☐ No Sidewalk shed required? ☒ Yes ☐ No
If yes, has a sidewalk shed been erected? ☒ Yes ☐ No If yes, provide permit number: 420252915
Does the building have fire escapes or other exits used jointly with an adjoining or abutting building? ☐ Yes ☒ No
Will the removal of the fire escape or other exit affect the adjoining building? ☐ Yes ☐ No
Does the building have party walls or walls enclosing an adjoining building? ☐ Yes ☒ No
If yes, please describe:
Has the demolition of the building commenced? ☐ Yes ☒ No If yes, answer the following questions:
Has work been stopped? ☐ Yes ☐ No Have the police been notified? ☐ Yes ☐ No
Has an ECB violation been issued? ☐ Yes ☒ No If yes, provide ECB violation number:
Comments: Bldg and lot (safety zone) conform to approved plans.
Inspection Result: ☒ Pass ☐ Fail
Inspected by: J W WERNEY Signature: J W WERNEY Badge # 2288 Date: 1-18-11
Supervisor: D M CUSANO Signature: D M CUSANO Badge # 1054 Date: 1/19/11
Administrative Comments:

safety • service • integrity

B-Form-2A (Rev. 11/06)

**APPROVED
BEST SQUAD**