

Franklyn Estrella, RA
Architecture Interior Design



October 8, 2013


Department of Buildings
Borough of Queens
120-55 Queens Blvd.
Kew Gardens, N.Y. 11424-1015

RE: 88-63 62 Drive
Block # 3107 Lot #117
Job# 420569986

To Whom It May Concern:

Please be advised that carbon monoxide detectors have been installed at the above premises are battery operated and have been installed within every habitable room and cellar as per with LL7/04 and Department of Buildings rules and regulations.

Yours truly,



Franklyn Estrella, RA