

Plumbing Division Sprinkler Inspection Report

DEPT BLDGS Job No. 421067053



Scan Code ESHS1174127

421067053 Premises 58-60 57ST Borough QUEENS Date 9/3/15
Approved Plan # XES Stories 2 Feet 32 When Installed August 5, 2015
Construction BRICK Occupancy COMM No. of water supplies 1 Area 20,000 Wet or Dry WET

Supply: City Water Connection Size 6" Fed 2 ways NA
Curb or P.I. Valve YES Name & size of meter 3/4" TRIDENT
Valves sealed open YES Lbs. Pressure 63 PSI

Gravity Tank Capacity NA Heated NA Height over top sprinkler line NA
Size fill line NA Size Overflow NA Emergency Drain Valve NA
Type and Size NA Tank piping brass NA Exposed piping weatherproofed NA
Ladder secured NA Location tank check and control valve NA
Valves sealed open NA No. Fill Pumps NA Size NA Type NA
Capacity in gallons NA How operated NA

Pressure Tank Capacity NA Tank House Heated NA Size Fill Line NA
Emergency Drain Valve NA Type and Size NA Air Pressure NA
Water Level NA Location tank check and control valves NA
Control valves sealed open NA

Risers No. 1 Size dead risers NA Size live risers 4"
Size drain risers 2" Floor control valves YES Sealed open YES
Main Drain YES Size 2" Location inspectors Test valve TOP FLOOR
Exposed Piping or Heads NA Location NA How protected NA
No. Cold Weather Valves NA Location NA App'd signs YES

No. Dry Valves NA Name NA Type NA Water Pressure NA
Air Pressure NA Dry Valve room heated NA
No. of heads controlled by each dry pipe valve NA

No. Alarm Valves NA Size and type NA Local NA Supervisory NA
High-Low Gravity NA High-Low Pressure NA Flow Alarm NA

Fire Pumps: Name NA Type NA Capacity in Gallons NA
Or NA
Booster Pumps: Checked NA Draws from NA Size of suction line NA
Size of discharge line NA How operated NA Supervisory NA
Adequate pressure in system NA

No. Siamese connections 1 Size 6x3x3 App'd Type YES
Location 57ST Signs YES Type of drips BALE
Caps painted green YES
Is every square foot of the building sprinklered YES
If not, portion sprinklered NA
Extra heads & wrench provided YES Painted or corroded heads NA

Is installation as per app'd plan YES As per Fire Dept. order NA
Entire system tested at 200 p.s.i. YES Result PASS
Certificate of Fitness required NA

Recommendations: NA

OWNER'S NAME AND ADDRESS	CONTRACTOR'S NAME AND ADDRESS
MARIZIO BARDONE 55-14 GRAND AVE MASPETH NY 11378	NYCO PLUMBING 30-84 35 ST ASTORIA 11103

Inspector (sign) Nicholas Yavalakis Inspector (print) NYCO PLUMBING

Test Listed
By

Report to: Div. Of Fire Prevention,
Fire Department