

5/2/16

APPLICATION FOR INSPECTION PRIOR TO DEMOLITION
(AND PRE-DEMOLITION REPORT)

Application must be typewritten.

BEST USE ONLY
DEMOLITION #

Applicant, please complete all information requested below: (For mechanical demolition requests complete form BEST-4 as well.)

Number of structures at this address you intend to demolish (a separate application is required for each):

Name: CHENG-SHENG HUANG Company: ZHENG & ASSOCIATES LLC

E-mail: ZHENGBUILDING@GMAIL.COM Phone: 7187622626 Fax: 718-762-2886

Application date: 04/03/2016 ☐ Bronx ☐ Brooklyn ☐ Manhattan ☒ Queens ☐ Staten IslandStructure type (check only one): ☒ House ☐ Garage ☐ Shed ☐ Commercial Building ☐ Other:Building address: 57-34 GAR 256 STREET Legalizing a completed demolition? ☐ Yes ☒ No


Cross streets: 57 AVE & 58 AVE BIN: 4492378 Block: 8345 Lot: 51

All AKA's ("Also-Known-As", if applicable):

BIS job # for demolition (DM) filing: Other related BIS job #s (if applicable):

Distance from nearest street corner (in feet): 293' Mechanical demolition requested? ☒ No ☐ Full ☐ Partial**BEST must be notified in writing 24 hours prior to the commencement of any demolition (see AC §27-195).**

PLOT DIAGRAM (MUST INDICATE ZONE OF SAFETY ON DIAGRAM)

The north point of the diagram
must agree with the arrow

Please see attached plot diagram.

A survey may be submitted in addition to or in lieu of a plot diagram as long as the zone of safety is indicated.

DO NOT WRITE BELOW THIS LINE: OFFICIAL USE ONLY

Date of report: 04-28-16 Number of stories: 1 Height of building: 16

Occupancy: Is building vacant? ☒ Yes ☐ No Sidewalk shed required? ☐ Yes ☒ NoIf yes, has a sidewalk shed been erected? ☐ Yes ☒ No If yes, provide permit number:Does the building have fire escapes or other exits used jointly with an adjoining or abutting building? ☐ Yes ☒ NoWill the removal of the fire escape or other exit affect the adjoining building? ☐ Yes ☒ NoDoes the building have party walls or walls enclosing an adjoining building? ☐ Yes ☒ No

If yes, please describe:

Has the demolition of the building commenced? ☐ Yes ☒ No If yes, answer the following questions:Has work been stopped? ☐ Yes ☒ No Have the police been notified? ☐ Yes ☒ NoHas an ECB violation been issued? ☐ Yes ☒ No If yes, provide ECB violation number:

Comments:

Inspection Result: ☒ Pass ☐ Fail

Inspected by: [Signature] Signature: [Signature] Badge # 2562 Date: 04-28-16

Supervisor: [Signature] Signature: [Signature] Badge # 1992 Date: 05/02/16

Administrative Comments:

