



EQ

EQ Non-Directive 14

INSPECTION REPORT

1. TYPE OF INSPECTION: EQ Non-Directive 14

2. RECORD INFORMATION

Record Type: DOB/Permit/EQ/NA

Record (Job/Permit/Application) #: 44030369001EQFN

Requestor Name: Nat Costanza

Requestor Phone Number: 5163023653

3. INSPECTION INFORMATION

Inspection Result: Pass

Inspection Date: 11/09/17 Inspection Time: 03:20 PM

Inspector Badge#: 1883

4. OBJECTIONS

Failed Guidesheet Item	Result	Certifiable?	Floor No.	Comments

5. APPROVAL

Inspection Final Result: _____

Inspection Final Approval Date: _____

Inspection Final Approval Time: _____

Supervisor Badge #: _____