



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) _____ **Control Number: 4766227**

2. Premise No. 129-15 Street Name 135 Street Borough Queens Zip 11420

3. AKA _____ Type of Facility Residence BIN 4255675 Block 11774 Lot 0537

4. Building Owner NYC Holding Group Address 129-15 135 Street

5. City Queens State NY Zip 11420 Contact Person Ali

6. Tel. # (646) 981-3839 Fax # _____ Email _____

7. Work Type PL Plumbing, General Construction

Description of the Entire Scope of Work

Interior renovation of an existing two family, two stories and cellar. Plumbing work as per plans. No change in bulk, egress or occupancy.

8. I, ROBERT COLQUHOUN, have conducted an asbestos investigation on
Name of Certified Asbestos Investigator

09/16/2020 10:00AM-10:45AM in accordance
Date(s)

with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☒ a. the premises or the portion(s) of the premises, included in the scope of renovations was/were determined that there was no asbestos-containing materials (ACM) present
- ☐ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
- ☐ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: _____ sq. ft _____ linear ft.
- ☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

Floor	Section of Floor(s) Surveyed	Material Assumed to Contain ACM and/or Sampled	Number of Samples Analyzed	Asbestos Present	Assumed ACM	Square Feet	Linear Feet	Abated	Scope of Work Applied
Building Floors-1 to 2	entire walls and ceiling	plaster	6	No	No				
Cellar	entire walls and ceiling	sheetrock	3	No	No				

I hereby declare the information provided herein is true and complete

ROBERT COLQUHOUN 9/21/2020 131788 2/20/2022
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (347) 220-5152 Fax # _____

Email rcolquhoun2000@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No





NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



10. ANALYTICAL LABORATORY:

NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
Saban Engineering	198.4	9/20/2020

11. NYS DOL Asbestos Handling license # 72943 Company Name Robert

12. Comment

I hereby declare the information provided herein is true and complete

ROBERT COLOUBOUN 9/21/2020 131788 2/20/2022
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (347) 220-5152 Fax # _____
Email colouhoun2000@gmail.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No



25794877