

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



1. NYC DOB Job # (if applicable) \_\_\_\_\_ **Control Number: 41015418**  
2. Premise No. 13169 Street Name 224th street Borough Queens Zip 11413  
3. AKA \_\_\_\_\_ Type of Facility Residence BIN 4278599 Block 12934 Lot 0107  
4. Building Owner Shanna Campbell Address 13169 224th street  
5. City Queens State NY Zip 11413 Contact Person Shanna Campbell  
6. Tel. # (973) 945-0130 Fax # \_\_\_\_\_ Email \_\_\_\_\_  
7. Work Type Other (Solar Panels)

**Description of the Entire Scope of Work**

Solar panels have to be installed on the roof via mechanical attachment penetrations (less than 10 sq. feet). Conduits of 2-3" in diameter will penetrate (less than 10 sq. feet.) entering the building's main electrical room. Small bolts will penetrate a wall inside of the electrical room to mount solar equipment. All penetrations will be less than 10 sq. feet.

8. I, MARK NAKHUMOVICH, have conducted an asbestos investigation on  
Name of Certified Asbestos Investigator  
08/13/2022 7:00AM-7:15AM Date(s) in accordance  
with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the  
☐ a. the premises or the portion(s) of the premises, included in the scope of renovations was/were determined that there was no asbestos-containing materials (ACM) present  
☒ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM. Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.  
☒ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: 950 sq. ft 0 linear ft.  
☐ d. entire building is free of asbestos containing material (ACM).

**9. RESULTS OF ASBESTOS BUILDING SURVEY:**

| Floor | Section of Floor(s) Surveyed | Material Assumed to Contain ACM and/or Sampled | Number of Samples Analyzed | Asbestos Present | Assumed ACM | Square Feet | Linear Feet | Abated | Scope of Work Applied |
|-------|------------------------------|------------------------------------------------|----------------------------|------------------|-------------|-------------|-------------|--------|-----------------------|
| Roof  | Roof, Electrical Room        | Roofing Shingles                               | 0                          | Yes              | Yes         | 700         |             | No     | c                     |

I have advised the Owner / owner's representative / client that the minor project amounts of the confirmed or presumed ACMs shall need to be abated by a NYS DOL Licensed Asbestos Abatement Contractor, and disposed of as asbestos-containing wastes, prior to conducting this renovation project.

I hereby declare the information provided herein is true and complete

MARK NAKHUMOVICH 8/17/2022 115626 9/4/2023  
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date  
Tel. # (917) 623-9274 Fax # (718) 247-9781  
Email mark@afamony.com




The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

Is it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No





NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION  
Asbestos Control Program  
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373  
**ASBESTOS ASSESSMENT REPORT**



|      |                       |             |   |     |     |     |    |   |
|------|-----------------------|-------------|---|-----|-----|-----|----|---|
| Roof | Roof, Electrical Room | Siding Wall | 0 | Yes | Yes | 250 | No | c |
|------|-----------------------|-------------|---|-----|-----|-----|----|---|

10. ANALYTICAL LABORATORY:

| NAME | ELAP # (NYS DOH CERTIFICATION) | DATE(S) SAMPLES ANALYZED |
|------|--------------------------------|--------------------------|
|------|--------------------------------|--------------------------|

11. NYS DOL Asbestos Handling license # 54835 Company Name Alamo Environmental Consulting Inc.

12. Comment

Warning: If during demolition/construction, a suspect asbestos containing material (ACM) (e.g. insulation, waterproofing or other) is observed in a hidden spaces, immediately stop any activity around it and call NYC DEP Asbestos Investigator (917-623-9274).

I have advised the Owner / owner's representative / client that the minor project amounts of the confirmed or presumed ACMs shall need to be abated by a NYS DOL Licensed Asbestos Abatement Contractor, and disposed of as asbestos-containing wastes, prior to conducting this renovation project.


I hereby declare the information provided herein is true and complete

MARK NAKHUMOVICH 8/17/2022 115626 9/4/2023  
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (917) 623-9274 Fax # (718) 247-9781

Email mark@alamonys.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-95-024 and 560/5-95-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # \_\_\_\_\_ ☒ No



251051172