



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373
ASBESTOS ASSESSMENT REPORT



1. NYC DOB Job # (if applicable) _____ **Control Number: 41091219**
2. Premise No. 87-50 Street Name 254 Street Borough Queens Zip 11426
3. AKA _____ Type of Facility Residence BIN 4176509 Block 08646 Lot 0052
4. Building Owner Kulwinder Singh Address 87-50 254th Street
5. City Bellerose State NY Zip 11426 Contact Person Kulwinder Singh
6. Tel. # (646) 964-7275 Fax # _____ Email skulwinder1997@gmail.com
7. Work Type Other (Solar)

Description of the Entire Scope of Work

Installation of solar system on the roof. (Any untested building materials in the area of work are assumed asbestos and should remain undisturbed.)

8. I, MARY HARTIGAN, have conducted an asbestos investigation on
Name of Certified Asbestos Investigator
02/24/2023 8:15AM-8:30AM in accordance
Date(s)

with Sections 1-16 and 1-28 of the NYC DEP Asbestos Control Program Rules and declare that at said facility address, the

- ☐ a. the premises or the portion(s) of the premises, included in the scope of renovations was/were determined that there was no asbestos-containing materials (ACM) present
- ☒ b. premise (or portions thereof) affected by the work contains 10 square feet or less or 25 linear feet or less of ACM.
Specify locations in section 9: Note: This material must be abated as a minor project in accordance with relevant provisions of the DEP Asbestos Rules.
- ☒ c. asbestos is present and will not be disturbed during construction activity. Specify the quantity and area where asbestos is present. Specify amount: 312 sq. ft 0 linear ft.
- ☐ d. entire building is free of asbestos containing material (ACM).

9. RESULTS OF ASBESTOS BUILDING SURVEY:

Floor	Section of Floor(s) Surveyed	Material Assumed to Contain ACM and/or Sampled	Number of Samples Analyzed	Asbestos Present	Assumed ACM	Square Feet	Linear Feet	Abated	Scope of Work Applied
Roof	Proposed Solar System Location Only	Misc. Roofing Material/Waterproofing	0	Yes	Yes	2		Yes	b

I have advised the Owner / owner's representative / client that the minor project amounts of the confirmed or presumed ACMs shall need to be abated by a NYS DOL Licensed Asbestos Abatement Contractor, and disposed of as asbestos-containing wastes, prior to conducting this renovation project.

I hereby declare the information provided herein is true and complete

MARY HARTIGAN 2/28/2023 120566 12/7/2024
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date
Tel. # (914) 494-2285 Fax # _____
Email mhartigan127@aol.com



The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.

Is it a Build-It-Back project? ☐ Yes, App ID # _____ ☒ No

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.






NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Flushing, NY 11373

ASBESTOS ASSESSMENT REPORT



Roof	Proposed Solar System Location Only	Misc. Roofing Material/Waterproofing	0	Yes	Yes	306		No	c
Roof	Proposed Solar System Location Only	Misc. Flashing/Waterproofing	0	Yes	Yes	6		No	c

10. ANALYTICAL LABORATORY:

NAME	ELAP # (NYS DOH CERTIFICATION)	DATE(S) SAMPLES ANALYZED
------	--------------------------------	--------------------------

11. NYS DOL Asbestos Handling license # 61539 Company Name Environmental Experts Inc.

12. Comment

No electrical or interior work is included on this ACP-5. Exterior of the house (Exterior Siding, Masonry, Mortar, Cementitious Material, Misc. Flashing/Waterproofing and Misc. Caulking/Waterproofing) is not included on this ACP-5, is assumed asbestos and should remain undisturbed. If these materials must be disturbed they should be treated like asbestos.

I have advised the Owner / owner's representative / client that the minor project amounts of the confirmed or presumed ACMs shall need to be abated by a NYS DOL Licensed Asbestos Abatement Contractor, and disposed of as asbestos-containing wastes, prior to conducting this renovation project.


I hereby declare the information provided herein is true and complete

MARY HARTIGAN  2/28/2023 120566 12/7/2024
DEP Certified Asbestos Investigator's Signature Date Certificate Number Expiration Date

Tel. # (914) 494-2285 Fax #

Email mhartigan127@aol.com

The investigator shall assume that some or all of the areas investigated contain ACM, and for each area that is not assumed to contain ACM, collect and submit for analysis bulk samples in accordance with §§ 1-36, 1-37, and 1-44 of the DEP Asbestos Rules and EPA publications 560/5-85-024 and 560/5-85-030a and 40 CFR 763.86.



Is it a Build-It-Back project? ☐ Yes, App ID # ☒ No



251130420

Note: There is always a possibility of existing ACM inside the wall, or above the ceiling, or under existing flooring. If any suspected ACM is found, all work should be stopped for reinspection.