



APPLICATION FOR INSPECTION PRIOR TO DEMOLITION
(AND PRE-DEMOLITION REPORT)


Application must be typewritten.

BEST USE ONLY
DEMOLITION #

Applicant, please complete all information requested below: (For mechanical demolition requests complete form BEST-4 as well.)

Number of structures at this address you intend to demolish (a separate application is required for each):		2
Name: William Formica	Company: Formica Construction, Inc.	
E-mail:	Phone: 718-720-4603	Fax: 718-720-0137
Application date: 2/9/12	☐ Bronx ☐ Brooklyn ☐ Manhattan ☐ Queens ☒ Staten Island	
Structure type (check only one): ☒ House ☐ Garage ☐ Shed ☐ Commercial Building ☐ Other:		
Building address: 881 Morrow Street SI, NY 10303		Legalizing a completed demolition? ☐ Yes ☒ No
Cross streets: Elizabeth Grove Road & Forest Ave BIN: 5028668		Block: 1384 Lot: 1
All AKA's ("Also-Known-As", if applicable):		
BIS job # for demolition (DM) filing: 520089993		Other related BIS job #s (if applicable): 520089984
Distance from nearest street corner (in feet): 0'		Mechanical demolition requested? ☐ No ☒ Full ☐ Partial
BEST must be notified in writing 24 hours prior to the commencement of any demolition (see AC §27-195).		

PLOT DIAGRAM (MUST INDICATE ZONE OF SAFETY ON DIAGRAM)



The north point of the diagram must agree with the arrow

See Tax map
& plans



A survey may be submitted in addition to or in lieu of a plot diagram as long as the zone of safety is indicated.

DO NOT WRITE BELOW THIS LINE: OFFICIAL USE ONLY

Date of report: 05/15/12	Number of stories: 02 1/2	Height of building: Approx 27 ft
Occupancy: Is building vacant? ☒ Yes ☐ No	Sidewalk shed required? ☐ Yes ☒ No	
If yes, has a sidewalk shed been erected? ☐ Yes ☒ No	If yes, provide permit number: NA	
Does the building have fire escapes or other exits used jointly with an adjoining or abutting building? ☐ Yes ☒ No		
Will the removal of the fire escape or other exit affect the adjoining building? ☐ Yes ☐ No NA		
Does the building have party walls or walls enclosing an adjoining building? ☐ Yes ☒ No		
If yes, please describe:		
Has the demolition of the building commenced? ☐ Yes ☒ No	If yes, answer the following questions:	
Has work been stopped? ☐ Yes ☐ No NA	Have the police been notified? ☐ Yes ☐ No NA	
Has an ECB violation been issued? ☐ Yes ☐ No NA	If yes, provide ECB violation number: NA	
Comments:		

Inspection Result: ☒ Pass ☐ Fail	
Inspected by: ISLAM	Signature: [Signature] Badge # 2342 Date: 05/14/12
Supervisor: DMcGee	Signature: [Signature] Badge # 162 Date: 5/17/12
Administrative Comments:	

