



AI1: Additional Information

Must be typewritten.

13-1473



Page number 1 of 2

BIS Document No. 01

1 Location and Job Information Required for all applications.

House No(s) 48 Street Name Greenport Street
Borough Staten Island Block 857 Lot 39 BIN 5022274 CB No. 502

2 Revisions to Plans/Drawings Required whenever updating plans. All revisions for each page must be clearly described in section 3.

Submission is part of a Post Approval Amendment (PAA)? ☐ Yes PW1 required ☒ No Indicate all actions for this submission:

Action	Original/New/ Omit Page ID	Superseding Page ID	Action	Original/New/ Omit Page ID	Superseding Page ID	Action	Original/New/ Omit Page ID	Superseding Page ID	Action	Original/New/ Omit Page ID	Superseding Page ID

For "Action" use "N" for new page, "S" for superseding page, "O" for omitting page.

Is this section continued on additional AI1 forms? ☐ Yes ☐ No


3 Additional Information Required for all applications.

Copy of DOB records from NB 1767/63 folder indicating original new building soil test pit results submitted herewith (see page 2). As per Department of Buildings TEST PITS - SOIL INSPECTION (Form 28), a test pit was performed on 7/16/63. Per inspection by the architect of record (7/24/63) and the NYCDOB inspector (8/12/63) the test pit results indicated compact sand-clay soils - 3 tons per square foot, Class No. 9. Such DOB documentation is sufficient to confirm the soil bearing capacity for the subject alteration.

*OK TO ACCEPT AS TEST PITS
FOR SECOND STORY ADDITION
10/1/13*

Falsification of any statement is a misdemeanor and is punishable by a fine or imprisonment, or both. It is unlawful to give to a city employee, or for a city employee to accept, any benefit, monetary or otherwise, either as a gratuity for properly performing the job or in exchange for special consideration. Violation is punishable by imprisonment or fine or both. I understand that if I am found after hearing to have knowingly or negligently made a false statement or to have knowingly or negligently falsified or allowed to be falsified any certificate, form, signed statement, application, report or certification of the correction of a violation required under the provisions of this code or of a rule of any agency, I may be barred from filing further applications or documents with the Department.

Name (please print) Stanley M. Krebushevski Date _____
Signature _____
P.E./R.A. Seal (attach seal, then sign and date over seal)



THE CITY OF NEW YORK
DEPARTMENT OF BUILDINGS

TEST PITS - SOIL INSPECTION


NOTE: This form shall be used to submit the record of test pits and the Architect's or Engineer's certification thereof for one-story buildings imposing an average load on the soil not exceeding 1,000 lbs. per square foot or dwellings not more than two stories in height or extensions. For all other buildings, including any on piles, boring records shall be submitted (Sec. C26-376.0, Adm. Code).

Re: Alt 1767/63 Borough Richmond Block 857 Lot 39

LOCATION: 4/8 Greenport Street N/S 195.71' East of Wooddale Ave., S.I. 4, N.Y.

No. of Bldgs. to be Erected	1	Height	21'	Occupancy	1 ram.dwell. & 1 car garage in basement
Area of Each Building	1360	Total Area All Bldgs.	1360	Number of Test Pits (Total Area in Square Feet Divided by 2500)	1

PLOT DIAGRAM



PLOT PLAN: Must be drawn in ink on an indicated scale, show the outline of the buildings or extension and the location of all test pits by dimensions. Test pits must be located within the area to be occupied by the buildings or extension and be spaced so that each requires not more than 2500 sq. ft. of building area.

To the Borough Superintendent:

have examined the test pits as shown and numbered on the plot diagram above and certify that the following is an accurate summary of my findings:

Date July 24, 1963

ARCHITECT OR ENGINEER

5265
REGISTRATION NO.

Plot No.	Date of Inspection	Depth Below Curb Level	Description of Soil	Class No. (C26-377.0)	Construction Inspector's Remarks
1	7/16/63	4'	Compact sand-clay soils 3 tons per sq. ft.	9	may need wall

TO THE CHIEF INSPECTOR:

TO THE CHIEF INSPECTOR: Aug 9, 1965
I have inspected all of the test pits at the above location on (date) Aug 9, 1965 and find that the information contained in the above tabulation is correct, except as noted by me in "Construction Inspector's Remarks" column above. I recommend a soil bearing value of 5 tons per square foot at level of 1 feet below curb subject to inspection after excavation and before any footings are placed.

Date Aug 12, 1965 Inspector [Signature] District No. 1