


[CLICK HERE TO SIGN UP FOR BUILDINGS NEWS](#)

NYC Department of Buildings

Electrical Application Details for App #: R148424

Premises: 388 MAIN STREET STATEN ISLAND

BIN: 5088201 Block: 7912 Lot: 27[DOB NOW: Inspections](#)**Application Completed and Certified**

Filed: 388 MAIN ST
ROOF/GROUND
STATEN IS, NY 10307

Census Tract: 244.01
Admin Area: R - STATEN ISLAND
Community Board: 503

Health Area: 0800
Inspection Area: E

DOB Cross Street(s): PITTSVILLE AVENUE, HYLAN BOULEVARD**Status:** C - JOB IS SIGNED OFF 07/08/2016**Request Type:** A - APPLICATION**eFiled:** YES**Permit Issued:** 05/24/2016 2:06 PM**Application Entered:** 05/24/2016**Job Start Date:** 05/24/2016**Last Change:** 07/08/2016**Job End Date:** 06/12/2016**Appointment Status:****Last Inspection By:** TREJO, JORGE **On** 06/25/2016**Field Disp:** C - INSPECTION PASSED**Energize Recommendation:****Objection Disposition:****License #:** 011068**Licensee Name:** CARLOS BERGER**Firm:** 003535**Firm Name:** BERGER QUALITY ELEC'L CON**Firm Phone:** 718-768-3300**Firm Address:** 195 7TH AVENUE D/B/A BRIGHTLINE ELECTRIC BROOKLYN NY 11215**Work Started or Filed by Others:** NO**Work Category:** R - REHABILITATION

Work To Be Done:
E - SUSTAINABLE ENERGY - SOLAR

Total Fee: \$153.00**Other Work:****Work Related to a New or Amended Certificate of Occupancy:** NO**This Job Regulated by the NYC Energy Conservation Code:** No**Building Used As:** A - One Family**Special Cert Approval:****Advisory Board Approval:** NOT APPLICABLE**Owner / Occup:** JOSEPH SCUTERI

388 MAIN ST STATEN ISLAND NY 10307

Authorized Representative:**Relationship To Owner:**

WORK DESCRIPTION

BUILDING OVERVIEW		Are Feeders Being Installed? : Yes
<i>(If feeders are being installed, provide a wiring diagram and calculations at the time of inspection)</i>		
Building Overview Work Items	QUANTITY	DESCRIPTION
SERVICE SWITCHES		
A. Up to 100 AMPS	1	60 AMP
B. 101 Up to 200 AMPS	0	
C. 201 Up to 600 AMPS	0	
D. 601 Up to 1200 AMPS	0	
E. Over 1200 AMPS	0	
SER. ENT. & FDR COND (EACH SET)		
A. Up to #2 CONDUCTOR	5	3#6,2X3#8,2X3#10
B. Over #2 to 1/0	0	
C. Over 1/0 to 250 MCM	0	
D. Over 250 MCM	0	
PANELS		
A. 1 Phase Up to 20-1 or 10-2 Pole Brkrs	2	1 PHASE 20-1
B. 1 Phase Over to 21-1 or 10-2 Pole Brkrs	0	
C. 3 Phase Up to 225 AMPS	0	
D. 3 Phase Over 225 AMPS	0	
ELEVATORS / ESCALATORS / MATERIAL LIFTS		
A. Total No. of Elevators / Escalators / Material Lifts	0	
B. Each Additional 10 Floors Or Less	0	
BOILER CONTROLS		
	0	

FLOOR DESCRIPTIONS

Floor	Apt.	Number Of Outlets				No. Of Fixtures	Motors / Generators		Heaters		Transformers	
		Fixt	Receptacles		Switch		Num	Total HP KW	Num	Total KW	Num	Total KVA
			ATT	A/C								
GND					1						1	9
Buildings Total					1							9
Total Units : 10 units												

Signs: Field Connect: 0 Field Inspect: 0 Tags:

SERVICE / METER EQUIPMENT

Meter Request to Utility		#3-Wire	0	#4-Wire	0	#10-Wire	0
Existing Meters	0	+ New Meters	0	- Removed Meters	0	= Total Meters	0

Power Auth Flag:
Power Requested:
Power Issued:

Objection Flag:
Notice:
Response:

Follow-Up: K - (CLOSED)

Contractor's Comments: WIRE SOLAR SYSTEM

Inspection Details

INSPECTION FOR APPLICATION #: R148424

INSP ID	FIELD DATE	DISP DATE	INSP ID	FLD DISP	OBJ DISP	ENRG REC	TIME INSP	REINSP DATE	NEW OBJ	APPT FLAG
(1)	06/25/2016	06/28/2016	JTE	C			(35)		(0)	Y
INSPECTION COMMENTS:			INSPECTION PASSED.							

If you have any questions please review these [Frequently Asked Questions](#), the [Glossary](#), or call the 311 Citizen Service Center by dialing 311 or (212) NEW YORK outside of New York City.